



0 500 1000 Feet

Explanation

- Proposed monitoring well
- EPA monitoring well
- Schlumberger monitoring well
- Lear monitoring well
- TCEQ monitoring well

- Total Cr above 10 µg/L
- Total Cr above 50 µg/L
- Total Cr above 100 µg/L

EA ENGINEERING,
SCIENCE, AND
TECHNOLOGY

WEST COUNTY ROAD 112
GROUND WATER PLUME SITE
MIDLAND COUNTY, TEXAS

**Proposed Additional
Monitoring Wells
Location Map**

DESIGNED BY
DWR

DRAWN BY
CRS

CHECKED BY
DWR

SCALE
1:12,000

DATE
08/30/2011

PROJECT NO
EPA6.0000.05

FIGURE
.